De-activated Standards - December 2021

Grouping	Grant Eligible Training Title	GET Code	From	To	Comments
Wood Floor Installation	Finish applications	GET1860	Active	inactive	Standard to be deactivated due to no longer required by industry/very low number of claims
Wood Floor Installation	Floor repair	GET1861	Active	inactive	Standard to be deactivated due to no longer required by industry/very low number of claims
Wood Floor Installation	Planning and estimating	GET1862	Active	inactive	Standard to be deactivated due to no longer required by industry/very low number of claims
Wood Floor Installation	Sanding	GET1863	Active	inactive	Standard to be deactivated due to no longer required by industry/very low number of claims
Wood Floor Installation	Strip and plank installation	GET1865	Active	inactive	Standard to be deactivated due to no longer required by industry/very low number of claims
Wood Floor Installation	Subfloor preparation for wooden floors	GET1866	Active	inactive	Standard to be deactivated due to no longer required by industry/very low number of claims
Wood Floor Installation	Wood science	GET1868	Active	inactive	Standard to be deactivated due to no longer required by industry/very low number of claims
Wood Occupations	Fire Door Inspection Scheme (FDIS) Foundation Module	GET1462	Active	inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant
Wood Occupations	Fire Door Inspection Scheme (FDIS) Timber Fire Doors and Frames	GET1463	Active	inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant
Wood Occupations	Fire Door Inspection Scheme (FDIS) Metal Fire Doors	GET1464	Active	inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant

Grouping	Grant Eligible Training Title	GET Code	From	To	Comments
Wood Occupations	Fire Door Inspection Scheme (FDIS) Glazing	GET1465	Active	inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant
Wood Occupations	Fire Door Inspection Scheme (FDIS) Seals	GET1466	Active	inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant
Wood Occupations	Fire Door Inspection Scheme (FDIS) Ironmongery and Signage (Part 1)	GET1467	Active	inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant
Wood Occupations	Fire Door Inspection Scheme (FDIS) Ironmongery and Signage (Part 2)	GET1468	Active	inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant
Surveying and setting out	Drone technology in the construction and engineering environments	GET2619	Active	Inactive	Deactivation due to being superseded by GET3039: Drone use for construction - Introduction and GET3040: Drone use for construction - Intermediate
Plastering	Laying Sand and Cement Screeds to Levels and/or Falls	GET1504	active	inactive	Standard to be deactivated as duplication of GET3030: Traditional screeds
Interior Systems	Apply wall coverings to interior systems	GET2689	active	inactive	Deactivation as standard already exists - GET2561: Hang wallcoverings to complex surfaces, GET2558: Introduction to paper hanging, GET2765: Wallpapering intermediate
Interior Systems	Dry Lining, Taping and Jointing	GET0208	active	inactive	Deactivation as duplicate to GET2694: Hand jointing and finishing
Interior Systems	The introduction to abrading surfaces including machine and hand sanding	GET1964	active	inactive	Deactivation as duplicate to GET2694: Hand jointing and finishing, GET2700: Mechanical jointing and finishing
Interior Systems	The application of filler/joint cement directly to plasterboard systems	GET1962	active	inactive	Deactivation as duplicate to GET2694: Hand jointing and finishing

Grouping	Grant Eligible Training Title	GET Code	From	To	Comments
Interior Systems	The introduction to measures/mixtures for drywall adhesive, joint filler, joint cement	GET1961	active	inactive	Deactivation as duplicate to GET2694: Hand jointing and finishing
Interior Systems	Interior Systems introduction to setting out of systems using traditional and modern instruments	GET2702	active	inactive	Standard to be withdrawn at request of sector
Painting and Decorating	Marbling Techniques Advanced	GET0292	active	inactive	Standard to be deactivated due to zero claims
Painting and Decorating	Painting Traditional Coatings to include 'Dead Flat Paints'	GET0287	active	inactive	Standard to be deactivated due to zero claims
Painting and Decorating	Replica Graining	GET0294	active	inactive	Standard to be deactivated due to zero claims
Painting and Decorating	Simple Wood Effects Introduction	GET0293	active	inactive	Standard to be deactivated due to zero claims
Utilities - Excavations	Safe digging practices (assured)	GET2175	active	inactive	Full standard to be uploaded at request of the sector = GET3113 Safe digging practices (assured)
Construction (common)	New rules of measurement (NRM2)	GET0045	active	inactive	Royal Institute of Chartered Surveyors (RICS) advise that New rules of measurement (NRM2) is a reference document and not a training standard
Surveying and setting out	Surveying and Setting Out Intermediate	GET0014	active	Inactive	Replaced/Superseded with GET2135: Levelling and setting out by tape and GET2178: Total Station for construction
Piling	Understanding and describing soils and rocks	GET1364	Active	Inactive	SID to be withdrawn as the title has been confirmed as out of scope for Short Duration Training Grant

De-activated Standards - December 2021

Grouping	Grant Eligible Training Title	GET Code	From	To	Comments
Rail	Stressing kit configuration	GET0415	Active	Inactive	Standard to be withdrawn not recognised by NSAR/Network Rail
Rail	Win ALC Geometry	GET0430	Active	Inactive	Standard to be withdrawn not recognised by NSAR/Network Rail
Rail	working under live OLE	GET0432	Active	Inactive	Standard to be withdrawn not recognised by NSAR/Network Rail
Rail	Tracked dumper operation	GET0436	Active	Inactive	Standard to be withdrawn not recognised by NSAR/Network Rail
Rail	Thermit Ocy lance gas cutting	GET0440	Active	Inactive	Standard to be withdrawn not recognised by NSAR/Network Rail
Rail	P6 Rail planning	GET0447	Active	Inactive	Standard to be withdrawn not recognised by NSAR/Network Rail
Rail	On Track Plant Attachments	GET0426	active	inactive	To be replaced with specific Network Rail on track plant (OTP) attachment titles, see GET3115 - GET3148 and refer to CITB website
Rail	Ap11 Fastclip Machine	GET0412	active	inactive	To be replaced with specific Network Rail on track plant (OTP) attachment titles, see GET3115 - GET3148 and refer to CITB website
Rail	Ballast Tamper	GET0675	active	inactive	To be replaced with specific Network Rail on track plant (OTP) attachment titles, see GET3115 - GET3148 and refer to CITB website